



ATTENTION: PLEASE READ

Date: January 14, 2026

Bulletin #: Bul-Prod-0126-068

Subject: **SPL250 LITE Series Repair Solution**

To: **All Neapco Drivelines Aftermarket Group Customers**



Neapco is pleased to announce the release of a new, simplified solution for repairing Spicer SPL[®]250 LITE drivelines. To repair these driveshafts today, you must replace the one-piece midship assembly with proprietary OEM components.

Through the development of a new set of adaptor sleeves, our innovative **N250-LITE KIT** replaces all OEM proprietary parts with readily available Neapco N250 series parts and allows independent aftermarket rebuilders to repair or assemble replacement driveshafts without having to rely on access to the OEM components.

Our unique solution:

- Creates the ability to repair SPL[®]250 LITE driveshafts with aftermarket standard components saving significant costs.
- Speeds the repair or replacement process by eliminating the glued-on center bearing.
- Enables the reuse of OEM weld yokes and tubing.

Unlike the OEM replacement center section, our solution comes with all needed components along with three new u-joints and hardware. After installing the N250-LITE KIT, individual components for the driveshaft can be more easily repaired or replaced.

To learn more about Neapco brand products please visit www.NeapcoAftermarket.com. Please contact your respective Neapco sales representative for any additional questions you might have regarding this outstanding new product offering.

Danielle Forton
Product Data Analyst

SPL Spicer[®]Life Series driveshafts is a registered trademark of Dana Limited



Neapco - New England Auto Products Corporation U.S.A. since 1921.
NeapcoAftermarket.com E-catalog and customer order portal: NeapcoParts.com